

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1407	(error detection correction).ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:36
S2	820	controller same plural\$4 near4 module same connect\$4 same bus\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 15:05
S3	1	S1 and S2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:22
S4	0	S3 and (error detection correction system data transmission plural\$4 module controller)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:24
S5	1	S3 and (error detection correction system data transmission plural\$4 module controller)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:45
S6	1	S5 and (circuit\$4 difference bit length correction capacity error detection correction switch\$4 kind length timing)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 13:46
S7	19	("3242465" "3462742" "3864670" "3921149" "3970995" "4021779" "4130866" "4309768").PN. OR ("4635186").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/06/11 13:33
S8	2	S7 and (error detection correction)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:36
S9	704	(error detection correction).ti. (error detection correction).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 15:10

EAST Search History

S10	2	S9 and error same transmission same module same buses	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:41
S11	1438630	(error detection correction).ti. (error detection correction).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 13:41
S12	122	S11 and error same transmission same module same buses	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:41
S13	45	S12 and plural\$4 near4 module	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 15:01
S14	34	S13 and connect\$4 near4 bus	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:43
S15	34	S13 and connect\$4 near4 bus\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 13:43
S16	34	S15 and (circuit\$4 difference bit length correction capacity error detection correction switch\$4 kind length timing)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 13:46
S17	1447	(error near3 detection near4 correction) same data near4 transmission	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 15:04
S18	6	S17 and (controller same plural\$4 near4 module same connect\$4 same bus\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 15:09
S19	64	plural\$4 near4 (error adj detection and module)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 15:09

EAST Search History

S20	1	S19 and S9	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:10
S21	66942	plural\$4 near4 module	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:12
S22	0	S21 and module same connect\$4 same plural\$4 near4 buses	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:13
S23	1532	S21 and module same connect\$4 same plural\$4 near4 buses	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:13
S24	74	S23 and (error detection correction)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 15:13
S25	54	S24 and controller same bus\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 15:39
S26	846	plurality near4 module near4 connect\$4 near4 (bus or buses or plural\$4 near4 bus)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 15:40
S27	10	S26 and (error near4 detection near4 correction near4 code)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 15:44
S28	5	S27 and switch	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 15:44
S29	5	S28 and (error detection correction system data transmission plural\$4 module controller)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:56

EAST Search History

S30	5	S29 and (information inspection error detection circuit bit length inspection)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:00
S31	5	S30 and control\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:30
S32	9280	(error detection correction code circuit switch\$4 length timing data transfer\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/06/11 16:33
S33	2	(error detection correction code circuit switch\$4 length timing data transfer\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 16:34
S34	3	(error detection correction code circuit switch\$4 timing data transfer\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 16:34
S35	29	(error detection correction code circuit switch\$4 data transfer\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 16:45
S36	19	S35 and error near4 detection near5 correction	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 16:46
S37	1	S35 and error near4 detection near5 correction near4 code same generat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:09
S38	1035	error near4 detection near5 correction near4 code same generat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 16:47
S39	0	S38 and error same depend\$4 same tranfer\$4 near4data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:51

EAST Search History

S40	0	S38 and error same depend\$4 same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:53
S41	0	S38 and error same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:51
S42	0	S38 and error same detection same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:52
S43	0	error near4 detection same depend\$4 same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:53
S44	0	error near4 detection same depend\$6 same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:54
S45	0	error same depend\$6 same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:57
S46	1	error near4 detection same correction same tranfer\$4 near4 data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 16:58
S47	7	S35 and error near4 detection near5 correction near4 code same data same transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:14
S48	59	error near2 detection adj correction near4 code generation circuit	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:23
S49	810	error near2 detection adj correction adj circuit	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:18

EAST Search History

S50	12	S48 and S49	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:18
S51	15	error near2 detection adj correction near4 code near4 generation near4 circuit	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:24
S52	1432	error near2 detection adj correction near4 circuit	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:24
S53	13	S51 and S52	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:27
S54	3	S53 and switch	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:30
S55	285	error adj detection/correction adj code	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:30
S56	27	S55 and error adj detection/correction adj circuit\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:31
S57	395	S26 and data near4 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:31
S58	12	S56 and data near4 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 17:32
S59	8	S58 and switch\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:38

EAST Search History

S60	0	error adj detection adj circuit\$4 near4 code same dependent same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:40
S61	0	error adj detection adj circuit\$4 near4 code same depend\$4 same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:40
S62	0	error adj (detection or corrction) adj circuit\$4 near4 code same depend\$4 same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:41
S63	29	error adj (detection or corrction) same code same depend\$4 same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:41
S64	8	error adj (detection or corrction) same circuit\$4 same code same depend\$4 same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:48
S65	3	error adj (detection or corrction) same circuit\$4 same switch\$4 same code same depend\$4 same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:49
S66	74	error adj (detection or corrction) same circuit\$4 same switch\$4 same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:52
S67	2	error adj (detection or corrction) same circuit\$4 same switch\$4 adj over same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:53
S68	3	error adj (detection or corrction) same switch\$4 adj over same data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:55
S69	53277	"714"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:56

EAST Search History

S70	12548	S69 and data near4 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:56
S71	17	S70 and dependent same timing same data same transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:57
S72	2	S71 and ECC	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 18:58
S73	5	S71 and error near4 correction	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:01
S74	42	(error detection and correction switch\$4 adj over data)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:02
S75	12	S69 and S74	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:07
S76	7	S75 and transfer\$4 same data	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:11
S77	1	error detection correction switch adj over (depend\$4 or occording) data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:13
S78	2	error detection correction switch adj over data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:14
S79	97	error detection correction switch\$4 data near5 transfer\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:14

EAST Search History

S80	33	S79 and "714"/\$.cls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/06/11 19:14
-----	----	-----------------------	---	------	----	------------------